

Weight	351 LBS
Max Auxiliary Pressure	3000 PSI
Max Flow at Max Pressure	29 GPM
Out-Put Shaft	2.5" Hex
Motor Port	-12 JIC
Suggested Machine Size	3.5 Ton - 12 Ton

Speed Chart

Flow GPM	Speed RPM
8	6
12	9
16	12
20	15
24	18
28	21

Reference Torque Chart

Pressure PSI	Torque FT-LBS
1000	4148
1200	4978
1400	5808
1600	6637
1800	7467
2000	8296
2200	9126
2400	9956
2600	10785
2800	11615
3000	12445

